

Airline Logo



**ECTM Status Report**

**MAY 2015**

Prepared by: Camilla Iversen      Reviewed by: Kristoffer Magersholt  
 Issued Date: 01-05-2015      WebECTM Rev. No. 3.2.2 – Build 22

**No remarks**  
**On watch**  
**Alert**

No	Aircraft	Eng Model	Installation	Pos	ESN	Last Upload	Status	Notes	Ref. No.
1	AC-FA1		EMB120						
		PW118		1	FA9935	25-04-2015	Green	No remarks	
		PW118		1	FA9952	25-04-2015	Green	No remarks	
2	AC-FAK2		EMB120						
		PW118		1	FA9947	21-04-2015	Yellow	Possible cold section problem	FA9947-FAK2-120315
		PW118		1	FA9955	21-04-2015	Green	No remarks	
3	AC-FAK3		EMB120						
		PW118		1	FA9911	26-04-2015	Green	No remarks	
		PW118		1	FA9959	26-04-2015	Green	No remarks	
4	AC-FAK4		EMB120						
		PW118		1	FA9961	19-04-2015	Green	No remarks	
		PW118		1	FA9917	19-04-2015	Red	Hot section problem, awaiting borescope result	FA9917-FAK4-150415
5	AC-FAK5		ATR42						
		PW121		1	FA9929	20-04-2015	Green	No remarks	
		PW120		1	FA9907	20-04-2015	Green	No remarks	
6	AC-FAK6		ATR72						
		PW124B		1	FA9910	20-04-2015	Yellow	ITT indication problem	FA9910-FAK6-120315
		PW124B		1	FA9988	20-04-2015	Green	No remarks	
7	AC-FAK7		ATR42						
		PW120		1	FA9984	19-04-2015	Green	No remarks	
		PW121		1	FA9909	19-04-2015	Green	No remarks	

EXAMPLE